Printed on: 7/19/2009 4:54:50 PM

National Transportation Safety Board			NTSB ID: DCA09IA064				Most Critical Injury: None				
PRELIMINARY REPORT			Occurrence Date: 06/23/2009			Investigated By: NTSB					
AY ATION			Occur	Occurrence Type: Incident							
Location/Time											
Nearest City/Place		State		Zip Code	Local Time		Time Zone				
Kagoshima					0303		UTC				
Aircraft Information											
Registration Number Aircraft Manufacturer						Model/Series Number					
N805NW	AIRBUS						A330-323				
Type of Aircraft: Airplane				Amateur Built Aircraft?							
Injury Summary: Fatal				Serious Minor				None		217	
Revenue Sightseeing Flight: No			Air Medical Transport Flight: No								

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On June 23, 2009, at 0303 UTC, an Airbus 330-323, U.S. registration N805NW, operated by Northwest Airlines as flight 8 from Hong Kong, China, to Tokyo, Japan, experienced an airspeed anomaly while in cruise flight at FL390 approximately 50 miles southwest of Kagoshima, Japan. The crew reported that they were in normal cruise at FL390 and in visual conditions with some convective weather displayed on radar about 25 miles north of track, with thin cirrus clouds ahead. After entering the cirrus and moderate precipitation and turbulence, the crew observed, and FDR confirms, the autopilot and autothrust switch off, and the aircraft switched to Alternate Law. The master caution and warning messages were activated. The crew followed flight manual procedures and the autopilot and normal law returned in about one minute, however the event quickly repeated itself, lasting for about 2 minutes. The crew turned the airplane 60 degrees off course to exit the weather as soon as the anomalous indications were observed. The autopilot, autothrust and other controls returned to functioning, but the airplane remained in alternate law for the rest of the flight. The crew observed, and FDR confirms, large airspeed fluctuations, small altitude fluctuations, and an overspeed alert. The flight continued to Tokyo, Narita airport and landed with no damage or injuries to the 9 crew and 208 passengers on board.

The incident occured in Japanese airspace, and the investigation was delegated to NTSB by the Japanese Transportation Safety Board, who assigned an Accredited Representative to the investigation.

Updated on Jul 7 2009 9:26AM

TRANSO
National Transportation Safety Board
0 7
PRELIMINARY REPORT
7
AVIATION

NTSB ID: DCA09IA064

reactional Transportation Safety De	our u						⊣					
PRELIMINARY REPORT		Occurrence Date: 06/23/2009										
AVIATION			Occurrence Type: Incident									
Other Aircraft Involved		ı										
Registration Number Aircraft Manufacturer							Model/S	Series Nun	nber			
Accident Information												
Aircraft Damage: None Acc					dent Occurred During:							
Crew Name					Certifica	te No.			Injury			
Pilot												
2												
3												
4												
5												
6												
Operator Information												
Name NORTHWEST AIRLINES INC			Opera	ator Desig	nator Code		iness As					
Street Address				City			State	Zip Code				
-Type of Certificate(s) Held:				Į.								
Air Carrier Operating Certificate(s):	Flag Carrier/Dor	mestic										
Operating Certificate:				О	Operator Certificate:							
Regulation Flight Conducted Under:	Non-U.S., Com	nmercial										
Type of Flight Operations Conducted	: Scheduled; Into	ernationa	al; Pas	senger (Only							
Flight Plan/Itinerary												
Type of Flight Plan Filed: IFR												
Last Departure Point					State	Airport Identifier						
Hong Kong												
Destination					State	Airport	dentifier	dentifier				
Tokyo												
Weather Information												
Investigator's Source: Company					acility ID: Observation T			tion Time	(Local):			
Sky/Lowest Cloud Condition:					Ft. AGL							
Lowest Ceiling:	g: Ft. AGL				Visibility: SM A			Altim	neter:	"F	Нg	
PRELIMINARY INFORMATION - SUBJECT TO CHANGE												

National Transportation Safety Board

NTSB ID: DCA09IA064

PRELIMINARY REPORT AYJATION		Occurre	nce Date: 06/23/2009							
		Occurrer	nce Type: Incident							
Weather Information (Continued from page 2)										
Temperature: °C	Dew Point:	°C Wind Direction:								
Wind Speed: Kts.	Gusts: Kt	ts. W	eather Conditions at Accident	ner Conditions at Accident Site: Instrument Conditions						
Administration Data				_						
Notification From Northwest				Date						
FAA District Office/Coordinator			Investigator-In-Charge William R. English	Investigator-In-Charge (IIC) William R. English						